

---

4 ALBERT EMBANKMENT  
LONDON SE1 7SR  
Telephone: +44 (0)20 7735 7611 Fax: +44 (0)20 7587 3210

MEPC.1/Circ.851  
7 January 2015

**IMPLEMENTATION AND ENFORCEMENT OF MARPOL ANNEX VI**

**Bunker delivery note and fuel oil sampling**

**Notes of protest received from 1 July 2014 to 31 December 2014**

- 1 Communications have been received from the Administrations of Cyprus and Liberia concerning the application of provisions under MARPOL Annex VI.
- 2 In accordance with the provisions of regulation 18.9.6 of MARPOL Annex VI, the above-mentioned communications, summarized in the annex, are circulated to Parties to the 1997 Protocol for their information and appropriate action, as well as to all IMO Members.
- 3 Reference should be made to MEPC.1/Circ.508 on *Bunker delivery notes and fuel oil sampling*, and resolution MEPC.182(59) on *2009 guidelines for the sampling of fuel oil for determination of compliance with the revised MARPOL Annex VI*.
- 4 For further details, please contact the flag State Administrations, the bunkering port Authorities or the marine fuel oil supplier.

\*\*\*



## ANNEX

SUMMARY OF NOTES OF PROTEST RELATED TO MARPOL ANNEX VI  
RECEIVED FROM JULY TO DECEMBER 2014

## Notes of protest received from the Administration of Cyprus

Name of ship, IMO number	Bunkering port, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
STOC MARCIA 9390305	Anchorage of Tongue, United Kingdom, 04.01.2014	V – Marine Fuels Tel.: +44 (0) 1689 883430 Fax: +44 (0) 1689 877666 Email: europe@vmarinefuels.com	The sulphur content on BDN: 1.00% m/m, The sulphur content after supplied and tested: 1.05% m/m
EMERALD 9004463	Antwerp, Belgium, 04.01.2014	TRANSCOR ENERGY N.V/S.A. Tel.: +32 2 389 9570 Fax: +32 3 575 8999 Email: bunker@transcor.be	The sulphur content on BDN: 0.987% m/m, The sulphur content after supplied and tested: 1.20% m/m
ARDEA 9503902	Off Gothenburg, Sweden, 11.01.2014	STENA OIL AB Tel: +46 (0)10 445 1410 Fax: +46 (0)31 129368 Email: bunkers@stenaoil.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
MERGUS 9503914	Gothenburg, Sweden, 14.01.2014	TOPOIL, SWEDEN Tel.: +46 3169 6150 Fax: +46 31691967 Email: linfoO@topoil.se	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
STOC MARCIA 9390305	Zelzate, Belgium, 19.01.2014	TRANSCOR ENERGY N.V/S.A. Tel.: +32 2 389 9570 Fax: +32 3 575 8999 Email: bunker@transcor.be	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m
STOC MARCIA 9390305	Riga, Latvia, 08.02.2014	MONJASA A/S Tel.: +45 70 260 230 Fax: +45 70 260 233 Email: Denmark@monjasa.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.05% m/m
SPARTO 9274800	Antwerp, Belgium, 06.02.2014	O. W. BUNKER (Belgium) N.V. Tel.: 03/2883600 Fax: 03/2341874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.03% m/m
TULIP 9521447	Rotterdam, Netherlands, 10.02.2014	Argos Bunkering B. V. Tel.: +31 (0)88 1007 630 Fax: +31 (0)88 1007 920 Email: bunkering@argosenergies.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.05% m/m
ARDEA 9503902	Off Gothenburg, Sweden, 14.02.2014	TOPOIL, SWEDEN Tel.: +46 3169 6150 Fax: +46 31691967 Email: linfoO@topoil.se	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
MERGUS 9503914	Antwerp, Belgium, 14.02.2014	O. W. BUNKER (Belgium) N.V. Tel.: 03/2883600 Fax: 03/2341874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.06% m/m
CMA CGM	Rotterdam,	Argos Bunkering B. V.	The sulphur content on BDN:

<b>Name of ship, IMO number</b>	<b>Bunkering port, Date</b>	<b>Supplier's Name, address, telephone number, etc.</b>	<b>Non-compliance issues</b>
UTRILLO 9192430	Netherlands, 14.02.2014	Tel.: +31 (0)88 1007 630 Fax: +31 (0)88 1007 920 Email: bunkering@argosenergies.com	0.99% m/m, The sulphur content after supplied and tested: 1.09% m/m
STOC MARCIA 9390305	Norrkoping, Sweden, 26.02.2014	PREEM AB Email: bunkers@preem.se	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.04% m/m
CMA CGM SAMBHAR 9295969	Rotterdam, Netherlands, 29.01.2014	Argos Bunkering B. V. Tel.: +31 (0)88 1007 630 Fax: +31 (0)88 1007 920 Email: bunkering@argosenergies.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.03% m/m
RN ARKHANGELSK 9384435	Arkhangelsk, Russian Federation, 27.02.2014	RN BUNKER Tel.: (495) 755 52 43 Fax: (495) 777 44 44	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.04% m/m
OCEAN 9457830	Gibraltar, United Kingdom, 05.03.2014	VEMAOIL COMPANY LIMITED Tel.: +350 40984 Fax: +350 74240 Email: vemaoil@gibriet.gi	The sulphur content on BDN: 0.84% m/m, The sulphur content after supplied and tested: 1.08% m/m
CMA CGM MANET 9224958	Rotterdam, Netherlands, 14.03.2014	V-Marine Fuels Tel.: +31(0) 10 436 0533 Email: europe@vmarinefuels.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
SPARTO 9274800	Rotterdam, Netherlands, 22.03.2014	Argos Bunkering B. V. Tel.: +31 (0)88 1007 630 Fax: +31 (0)88 1007 920 Email: bunkering@argosenergies.com	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.03% m/m
STOC MARCIA 9390305	Zelzate, Belgium, 25.03.2014	TRANSCOR ENERGY N.V/S.A. Tel.: +32 2 389 9570 Fax: +32 3 575 8999 Email: bunker@transcor.be	The sulphur content on BDN: 0.95% m/m, The sulphur content after supplied and tested: 1.06% m/m
CMA CGM MANET 9224958	Savannah, United States, 31.03.2014	COLONIAL MARINE FUELS Tel.: (415) 268 2700 Fax: (415) 268 2701	The sulphur content on BDN: 0.69% m/m, The sulphur content after supplied and tested: 1.06% m/m
STOC MARCIA 9390305	Zelzate, Belgium, 14.04.2014	TRANSCOR ENERGY N.V/S.A. Tel.: +32 2 389 9570 Fax: +32 3 575 8999 Email: bunker@transcor.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
RN MURMANSK 9384447	Arkhangelsk, Russian Federation, 13.04.2014	RN BUNKER Tel.: (495) 755 52 43 Fax: (495) 777 44 44	The sulphur content on BDN: 0.981% m/m, The sulphur content after supplied and tested: 1.04% m/m
MERGUS 9503914	Gothenburg, Sweden, 16.04.2014	TOPOIL, SWEDEN Tel.: +46 3169 6150 Fax: +46 31691967 Email: linfoO@topoil.se	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m

Name of ship, IMO number	Bunkering port, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
ORCHID 9624079	Gibraltar, United Kingdom, 03.05.2014	Bominflot (Gibraltar) Ltd. Tel.: +350 20047616 Fax: +350 20047618	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.04% m/m
THERMAIKOS 9114189	Benghazi, Libya*, 01.05.2014	BREGA PETROLEUM MARKETING CO	The supplier failed to comply with the regulation 18.5 and Appendix V of MARPOL Annex VI as BND did not contain the required information as IMO No. of vessel, Port of supply, Tel. No., Product name, Sulphur content, Declaration signed and certified by the fuel oil supplier's representative that the fuel oil supplied is in conformity with regulation 14.1 or 14.4 and regulation 18.3 of this Annex. Sample did not accompany the bunker delivery note.
STOC MARCIA 9390305	Zelzate, Belgium, 05.05.2014	OIL CHART Tel.: +32 32325234 Fax: +32 32336745 Email: info@oilchart.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.08% m/m
TULIP 9521447	Rotterdam, Netherlands, 05.05.2014	TREFOIL TRADING B.V. Tel.: +31 (0) 10 411 3315 Fax: +31 (0) 10 412 9989 Email: bunkers@trefoil.nl	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.06% m/m
UASC JUBAIL 9401063	Singapore, Singapore, 08.05.2014	CONSORT BUNKERS PTE LTD/ reg. No 198802125N Tel.: +6344 3008 Fax: +6344 5745	The sulphur content on BDN: 3.48% m/m, The sulphur content after supplied and tested: 3.55% m/m
PANTELIS 9274616	Ust Luga Anchorage No. 11 Russian Federation 07.05.2014	LUKOIL – RUSSIA Tel.: (812) 346 8131/8130 Fax: (812) 346 8132 Email: bunker@lukneva.ru	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
CMA CGM UTRILLO 9192430	Rotterdam, Netherlands, 13.05.2014	TRANSCOR ENERGY Tel.: +32 2 389 9570 Fax: +32 3 575 8999 Email: bunker@transcor.be	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m
POLAR DUKE 9378204	Den helder, Netherlands, 16.05.2014	GOLDEN ARROW Tel.: +31 20 684 4299 Fax: +31 20 684 6857 Email: bunkers@goldenarrow.nl	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.6% m/m
ARDEA 9503902	Naantali, Finland, 24.05.2014	NESTE OIL OY	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m

\* Not Party to the 1997 Protocol (MARPOL Annex VI) at the time of the bunkering.

Name of ship, IMO number	Bunkering port, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
ARDEA 9503902	Naantali, Finland, 24.05.2014	NESTE OIL OY	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
HELMUT 9354466	Antwerp, Belgium, 25.05.2014	TRANSCOR ENERGY N.V/S.A. Tel.: +32 2 389 9570 Fax: +32 3 575 8999 Email: bunker@transcor.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.08% m/m
THERMAIKOS 9114189	Benghazi, Libya*, 25/26.05.2014	AZZAWIY OIL REFINING. Co.INC	The supplier failed to comply with the regulation 18.5 and Appendix V of MARPOL Annex VI as BND did not contain the required information as IMO No. of vessel, Port of supply, Tel. No., Product name, Sulphur content, Declaration signed and certified by the fuel oil supplier's representative that the fuel oil supplied is in conformity with regulation 14.1 or 14.4 and regulation 18.3 of this Annex. Sample did not accompany the bunker delivery note.
EMERALD 9004463	Antwerp, Belgium, 25.05.2014	O. W. BUNKER (Belgium) N.V. Tel.: 03/2883600 Fax: 03/2341874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.10% m/m
ORCHID 9624079	St. Petersburg, Russian Federation, 27.05.2014	LUKOIL – RUSSIA Tel.: (812) 346 8131/8130 Fax: (812) 346 8132 Email: bunker@lukneva.ru	The sulphur content on BDN: 0.944% m/m, The sulphur content after supplied and tested: 1.07% m/m
MERGUS 9503914	Gothenburg, Sweden, 31.05.2014	TOPOIL, SWEDEN Tel.: +46 3169 6150 Fax: +46 31691967 Email: linfoO@topoil.se	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
CMA CGM BERLIOZ 9222297	Rotterdam, Netherlands, 28.05.2014	TRANSCOR ENERGY N.V/S.A. Tel.: +32 2 389 9570 Fax: +32 3 575 8999 Email: bunker@transcor.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.06% m/m
STOC MARCIA 9390305	Zelzate, Belgium, 06.06.2014	TRANSCOR ENERGY Tel.: +32 2 389 9570 Fax: +32 3 575 8999 Email: bunker@transcor.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.06% m/m
CMA CGM MANET 9224958	Rotterdam, Netherlands, 10.06.2014	V-Marine Fuels Tel.: +31(0) 10 436 0533 Email: ara@vmarinefuels.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m

\* Not Party to the 1997 Protocol (MARPOL Annex VI) at the time of the bunkering.

Name of ship, IMO number	Bunkering port, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
ARDEA 9503902	Rotterdam, Netherlands, 15.06.2014	O. W. BUNKER (Belgium) N.V. Tel.: +31 10 7891111 Fax: +31 10 495 5540 Email: owbunker@owbunker.nl	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.02% m/m
STOC MARCIA 9390305	Zelzate, Belgium, 18.06.2014	TRANSCOR ENERGY Tel.: +32 2 389 9570 Fax: +32 3 575 8999 Email: bunker@transcor.be	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.06% m/m
CMA CGM MATISSE 9192428	Philadelphia, United States, 18.06.2014	AEGEAN BUNKERING (USA) LLC 299 PARK AVENUE, 2nd Floor New York, NY 10171, United States	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m
MERGUS 9503914	Reykjavik, Iceland, 24.06.2014	Oliudreifing ehf Tel.: +354 440 1000 Email: n1@n1.is	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
SPARTO 9274800	Gothenburg, Sweden, 28.06.2014	STENA OIL AB Tel: +46 (0)10 445 1410 Fax: +46 (0)31 129368 Email: bunkers@stenaoil.com	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.03% m/m
MERGUS 9503914	Gothenburg, Sweden, 30.06.2014	TOPOIL, SWEDEN Tel.: +46 3169 6150 Fax: +46 31691967 Email: linfoO@topoil.se	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.01% m/m

**Notes of protest received from the Administration of Liberia**

Name of ship, IMO number	Bunkering port, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
ILSE WULFF 9401271	Tanjong Pelepas, Malaysia, 19.07.2014	Shell Eastern Trading (PTE) LTD, Shell house, 93 Clemenceau Avenue, Singapore, 239920 Tel: +65 6215 1407	The sulphur content on BDN: 3.43% m/m, The sulphur content after supplied and tested: 3.63% m/m
COSTA RICAN STAR 9150822	Antwerp, Belgium, 21.07.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.96% m/m, The sulphur content after supplied and tested: 1.04% m/m
NS BURGAS 9411202	Rotterdam, Netherlands, 17.07.2014	Trefoil Trading B.V. Glashaven 49, 3011 XG Rotterdam, Netherlands, Tel: +30 10 411 3315 Fax: +31 10 412 9989 Email: bunkers@trefoil.nl	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.03% m/m

Name of ship, IMO number	Bunkering port, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
PATRAIKOS 9442172	Singapore, Singapore, 20.07.2014	Wired Bunkering PTE LTD, 101 Thomson Road, #20-01, United Square, Singapore 307591, Singapore, Tel: +65 6333 6687 Fax: +65 6333 6695	The sulphur content on BDN: 3.43% m/m, The sulphur content after supplied and tested: 3.58% m/m
GENMAR KARA G 9302994	Rotterdam, Netherlands, 19.07.2014	V-Marine Fuels B.V., Westzeedijk 92, 3016 AG Rotterdam, Netherland Tel: +31 10 436 0533 Email: europe@vmarinefuels.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
TAVRICHESKY BRIDGE 9292060	Rotterdam, Netherlands, 16.07.2014	Aegean North West Europe, Nijverheidsstraat 7, B-2960 St. Job in't Goor, Belgium Tel: +32 3 652 0608 Fax: +32 3 652 1422 Email: ara.bunkers@apni.com	The sulphur content on BDN: 0.90% m/m, The sulphur content after supplied and tested: 1.04% m/m
CARIBBEAN STAR 9150810	Antwerp, Belgium, 14.07.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2, 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
PISCES STAR 9237773	Rotterdam, Netherlands, 26.11.2013	Argos Bunkering B.V., Waalhaven Z.Z. 11, 3089 JH, Rotterdam, Netherland Tel: +31 88 1007 630 Fax: +31 88 1007 920 Email: bunkering@argosenergies.com	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.08% m/m
HARM 9568562	Singapore, Singapore, 05.07.2014	Tankoil Marine Services PTE LTD, NO.1 Tras Link, #02-08, Orchid Hotel Singapore 078867, Singapore, Tel: +65 6273 0171 Fax: +65 6444 4045	The sulphur content on BDN: 2.48% m/m, The sulphur content after supplied and tested: 3.60% m/m
HANSA PAPENBURG 9357858	Singapore, Singapore, 12.05.2014	Bunker House Petroleum PTE LTD, 10 Anson Road, #20-15, International Plaza Singapore 079903, Singapore, Tel: +65 6222 0337 Fax: +65 6222 5721	The sulphur content on BDN: 3.43% m/m, The sulphur content after supplied and tested: 3.64% m/m



Name of ship, IMO number	Bunkering port, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
HANSA SIEGBURG  9401661	Hong Kong, Hong Kong, China, 20.05.2014	Taimin Petroleum & Chemicals Limited, Unit 2905-08, 29th floor, Shui On Centre, 6-8 Harbour Road, Wanchai, HK, Hong Kong, China, Tel: +852 2369 2332 Fax: 852 2366 8236	The sulphur content on BDN: 2.78% m/m, The sulphur content after supplied and tested: 3.55% m/m
HANSA SIEGBURG  9401661	Jebel Ali, United Arab Emirates*, 03.07.2014	AL Mahir Fuel Trading L.L.C. P.O. Box 13073, Ras Al Khaimah, United Arab Emirates, Tel: +971 9 2564390 Fax: +971 52 9899901 Email: info@almahirfuel.com	The sulphur content on BDN: 3.28% m/m, The sulphur content after supplied and tested: 3.69% m/m
COLOMBIAN STAR  9172480	Antwerp, Belgium, 07.07.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2, 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
COLOMBIAN STAR  9172480	Antwerp, Belgium, 09.06.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2, 2000, Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
COTE D'IVOIRIAN STAR  9172478	Antwerp, Belgium, 02.07.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2, 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
CMA CGM TOPAZ  9397602	Tanjong Pelepas, Malaysia, 19.07.2014	Equatorial marine fuel management services Pte Ltd, 9 Temasek Boulevard, #04-01, Suntec Tower Z, Singapore 038989, Singapore, Tel: +65 6259 1314 Fax: +65 6259 0760	The sulphur content on BDN: 3.45% m/m, The sulphur content after supplied and tested: 3.75% m/m
NS CLIPPER  9341081	Rotterdam, Netherlands, 02.10.2013	Rotterdam Marine Fuels ---	The sulphur content on BDN: 0.95% m/m, The sulphur content after supplied and tested: 1.04% m/m

\* Not Party to the 1997 Protocol (MARPOL Annex VI) at the time of the bunkering.

Name of ship, IMO number	Bunkering port, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
COSTA RICAN STAR  9150822	Antwerp, Belgium, 23.06.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2, 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
CMA CGM JASPER  9397614	Singapore, Singapore, 11.06.2014	Total Marine Fuels, 250 North Bridge Road, #39- 00, Rafflea City Tower, Singapore 179101, Singapore, Tel: +65 6849 4319 Fax: +65 6337 9483 Email: marine- fuels.singapore@lotse.com	The sulphur content on BDN: 3.41% m/m, The sulphur content after supplied and tested: 3.64% m/m
AFRIC STAR  8713562	Balboa, Panama, 07.05.2014	Peninsula Petroleum Panama, Inc., P.H. Office One, Calle 58 Obarroi y Calle 50, Floor 12, Suite #1202, Republic of Panama, Email: bunkers@peninsulapetroleum. com	The sulphur content on BDN: 3.44% m/m, The sulphur content after supplied and tested: 3.52% m/m
COLOMBIAN STAR  9172480	Antwerp, Belgium, 04.08.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
COTE DIVOIRIAN STAR  9172478	Antwerp, Belgium, 29.07.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.01% m/m
KM KEELUNG  9461087	Vlissingen, Netherlands, 11.08.2014	Oil Chart, Plantinkaai 13, 2000 Antwerpen, Belgium Tel.: +32 3 232 5234 Fax: +32 3 233 5745 Email: info@oilchart.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.08% m/m
DORIC PIONEER  9637117	Rotterdam, Netherlands, 03.08.2014	Transcor Energy N.V./S.A., Parc de L'Alliance, Boulevard de France 7, B-1420 Braine- J'Allcod, Belgium, Tel: +32 2 389 9570 Fax: +32 3 575 8999 Email: bunker@transcor.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m

Name of ship, IMO number	Bunkering port, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
COSTA RICAN STAR  9150822	Antwerp, Belgium, 18.08.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
HELLE RITSCHER  9333371	Rotterdam, Netherlands, 13.08.2014	O.W. Bunker (Netherlands) B.V., NL_3087 BM Rotterdam, Tel.: +31 10 789 1111 Fax: +31 10 495 5540 Email: owbunker@owbunker.nl	The sulphur content on BDN: 0.96% m/m, The sulphur content after supplied and tested: 1.01% m/m
NAVIGATOR SATURN  9177569	Vlissingen, Netherlands, 23.08.2014	Aegean North West Europe, Nijverheidsstraat 7, B-2960 St. Job in't Goor, Belgium Tel: +32 3 652 0608 Fax: +32 3 652 1422 Email: ara.bunkers@apni.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.14% m/m
PRIMORSKY PROSPECT  9511533	Rotterdam, Netherlands, 26.07.2014	Wiljo, Verbindingsdok 12A, Westkaai, 200 Antwerpen, Belgium Tel: +32 3 232 39 10 Fax: +32 3 232 56 47 Email: wiljo@wiljo.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.03% m/m
NS LOTUS  9439321	New York, United States, 25.05.2014	Phillips, 600 North Dairy Ashford, P.O. Box 4428, Houston, the United States, Tel: +1 280 2931000	The sulphur content on BDN: 0.996% m/m, The sulphur content after supplied and tested: 1.06% m/m
CHEMTRANS MOON  9270488	Los Angeles, United States, 25.07.2014	Chemoil Corporation, 4 Embarcadero Center, San Francisco, CA 94111, United States Tel: +1 415 268 2700 Fax: +1 415 268 2701 Email: ops@chemoil.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.01% m/m
COSTA RICAN STAR  9150822	Antwerp, Belgium, 17.09.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2, 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
CARIBBEAN STAR  9150810	Antwerp, Belgium, 12.08.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2, 2000, Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m

Name of ship, IMO number	Bunkering port, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
COLOMBIAN STAR  9172480	Antwerp, Belgium, 02.09.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2, 2000, Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.08% m/m
KM KEELUNG  9461087	Skagen, Denmark, 27.08.2014	Monjasa A/S, Strevelinsvej 34, DK-7000, Fredericia, Denmark Tel: +45 70 260 230 Fax: +45 70 260 233 Email: denmark@monjasa.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
VIKING EAGLE  9344954	Jacksonville, United States, 16.10.2014	Colonial Marine Fuels, 4 Embarcadero Center, San Francisco, CA 94111, United States Tel: +1 415 268 2700 Fax: +1 415 268 2701	The sulphur content on BDN: 0.949% m/m, The sulphur content after supplied and tested: 1.01% m/m
AVILA STAR  8713550	St. Petersburg, Russian Federation, 13.10.2014	Lukoil, Ul. Fokina 5, St Petersburg, Russian Federation Tel: +7 812 346 8130 Fax: +7 812 346 8132 Email: bunker@lukneva.ru	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.07% m/m
COLOMBIAN STAR  9172480	Antwerp, Belgium, 30.09.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2, 2000, Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.01% m/m
DORIC PIONEER  9637117	Rotterdam, Netherlands, 17.10.2014	LUKOIL Benelux B.V., Wihelminakade 85, 3072 AP, Rotterdam, the Netherlands Tel. +31 10264 2700 Fax: +31 10264 2750 Email: bunkers@lukoil.nl	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.05% m/m
COTE D'IVOIRIAN STAR  9172478	Antwerp, Belgium, 24.09.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
NEVSKIY PROSPECT  9256054	Gothenburg, Sweden, 30.11.2014	STENA OIL AB, P.O.BOX 4088, SE-400 40 Gothenburg, Sweden Tel.: +46 10 445 1410 Fax: +46 31 129 368 Email: bunkers@stenaoil.com	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m

Name of ship, IMO number	Bunkering port, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
COLOMBIAN STAR  9172480	Antwerp, Belgium, 22.11.2014	Ocean Energy Belgium, Maritime House Noorderlaan 111, 2030, Antwerpen, Belgium, Tel: +32 3 301 0341 Fax: +32 3 301 0342 Email: info@oceanenergy.be	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.05% m/m
CARIBBEAN STAR  9150810	Antwerp, Belgium, 03.11.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.03% m/m
COTE D'IVOIRIAN STAR  9172478	Antwerp, Belgium, 16.11.2014	Ocean Energy Belgium, Maritime House Noorderlaan 111, 2030, Antwerpen, Belgium, Tel: +32 3 301 0341 Fax: +32 3 301 0342 Email: info@oceanenergy.be	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.04% m/m
COSTA RICAN STAR  9150822	Antwerp, Belgium, 09.11.2014	Ocean Energy Belgium, Maritime House Noorderlaan 111, 2030, Antwerpen, Belgium, Tel: +32 3 301 0341 Fax: +32 3 301 0342 Email: info@oceanenergy.be	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.03% m/m
COLOMBIAN STAR  9172480	Antwerp, Belgium, 27.10.2014	O.W. Bunker (Belgium) N.V., Tavernierkaai 2 2000 Antwerpen, Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 Email: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
HONDURAS STAR  8906975	Antwerp, Belgium, 22.11.2014	Ocean Energy Belgium, Maritime House Noorderlaan 111, 2030, Antwerpen, Belgium, Tel: +32 3 301 0341 Fax: +32 3 301 0342 Email: info@oceanenergy.be	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.05% m/m
CARIBBEAN STAR  9150810	Antwerp, Belgium, 30.11.2014	Ocean Energy Belgium, Maritime House Noorderlaan 111, 2030, Antwerpen, Belgium, Tel: +32 3 301 0341 Fax: +32 3 301 0342 Email: info@oceanenergy.be	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.07% m/m